EPA/MEW All Parties Meeting

May 6, 2014

Agenda





- Introductions
- EPA Presentation: Sewer information along Fairchild Drive
- Further Assessment Potential Impacts and Potential Mitigation Measures – Discussion
- EPA Updates
- Other Items


Information Reviewed




- Coordination with City of Mountain View GIS, sewer lines, videos, video logs
- Manhole vapor sampling
- Selected sewer samples
- Current permitted industrial waste water disharges










Example video: F6-037 to F6-035







Example: F7-002 to F7-037







Manhole Number: F7-002

(13.3) - WATER INFILTRATION

(38.9) - WATER INFILTRATION -

(44.0) - WATER INFILTRATION

(48.9) - WATER INFILTRATION -

(120.9) - WATER INFILTRATION -

(125.3) - WATER INFILTRATION -

(129.7) - WATER INFILTRATION -

(140.8) - WATER INFILTRATION

(141.7) - lateral LEFT GREASE -

(154.4) - WATER INFILTRATION -

(160.4) - WATER INFILTRATION -

(181.0) - WATER INFILTRATION -

(226.9) - WATER INFILTRATION -

(230.7) - WATER INFILTRATION -

(241.5) - WATER INFILTRATION -

(294.7) - END INSPECTION

Total Distance: 294.7



Manhole Number: F6-037

Discussion



- Further Assessment
- Potential Impacts
- Potential Mitigation Measures
- Next Steps

EPA Update



- Community Involvement Activities
 - EPA Open House Wed, May 7, 2014 5:30-8:30 pm
- Meeting with SCDEH and SCPHD
- Other Updates